

Spare Parts used in Waters@Kallang Place

June 2020 Calibration

|           |    |        |
|-----------|----|--------|
| SUM       | \$ | 810.96 |
| COA       | \$ | 81.10  |
| Total sum | \$ | 892.06 |

| S/N | Date      | DESCRIPTION                    | Part no        | BAAN No.       | Quantity | Cost (US\$)/EA | Remarks                                                                                                                      |
|-----|-----------|--------------------------------|----------------|----------------|----------|----------------|------------------------------------------------------------------------------------------------------------------------------|
| 1   | 20-May-20 | ASSY, CABLE, THERMAL SWITCH    | WAT-441001453  | WAT-441001453  | 1        | \$ 1.6600      | For 2998 detector(golden unit) p/n: 186002998 s/n: D089980406A due to noise failure.(For Spare bench P/n: 700011867)         |
| 2   | 20-May-20 | ASSY, CABLE TEMPERATURE SENSOR | WATH-279001871 | WATH-279001871 | 1        | \$ 41.1700     | For PDA detector(golden unit) p/n: 186005032 s/n: BETUPD008N due temperature sensor failure.(For Spare bench P/n: 700011652) |
| 3   | 29-May-20 | ASSY, HB DEUTERIUM LAMP        | WAT-402000351  | WAT-402000351  | 5        | \$ 153.6260    | For 2489 detectors 186248900 s/n: H1387E728A,H1387E733A,H1387E732A,H1387E736A and D1387E766A due to expiry of lamp hours.    |