



Altus A-10 System Software Release Notes

Release #010, 6 April 2015

Contents:

The following instruments are included in this release:

A-10 Module Name	Instrument Type Name	ICS Version	Firmware Version	Checksum
A-10 Solvent and Sampling Module	W2695/5	N/A	1.0	0xb329f58c
A-10 UV Detector	A10-UV	1.00.5139	1.0	0xbd11d075
A-10 PDA Detector	A10-PDA	1.00.5127	1.0	0xeddf5253
A-10 RI Detector	A10-RI	1.00.5131	1.0	0x504bca15
A-10 FL Detector	A10-FL	1.00.5088	1.0	0xdf6368cd

NOTES:

Firmware – All instruments must be updated with the new firmware using Autoloader

A-10 SSM Firmware – If updating firmware from a Waters Separations Module for the first time (internal only), the SSM firmware must be updated manually using autoloader and manually selecting the firmware from the deployment firmware folder.

Verified TCRs – Areas of the software which can now be officially evaluated

"Id"	"Primary Product"	"Title"
"31569"	"A-10 FL"	"Startup and Shutdown"
"31570"	"A-10 FL"	"Instrument Front Panel"
"31571"	"A-10 FL"	"Naming"
"31572"	"A-10 FL"	"Control Panel"
"31574"	"A-10 FL"	"Console - System Page"
"31575"	"A-10 FL"	"Console - Instrument Page"
"31576"	"A-10 FL"	"Console - Control Menu"
"31577"	"A-10 FL"	"Console - Configure menu"
"31578"	"A-10 FL"	"Console - Maintain menu"
"31579"	"A-10 FL"	"Console - Troubleshoot Menu"
"31580"	"A-10 FL"	"Console - Help Menu"
"31581"	"A-10 FL"	"Method Editor"
"31582"	"A-10 FL"	"Acquisition"
"31583"	"A-10 FL"	"Reporting"
"31584"	"A-10 FL"	"Error Reporting"
"31585"	"A-10 FL"	"Online Help"
"31586"	"A-10 FL"	"Firmware"
"31874"	"A-10 FL"	"Installer"
"31550"	"A-10 PDA"	"Startup and Shutdown"
"31551"	"A-10 PDA"	"Front Panel"
"31552"	"A-10 PDA"	"Naming"
"31553"	"A-10 PDA"	"Instrument Control Panel"
"31554"	"A-10 PDA"	"Console - System Page"
"31555"	"A-10 PDA"	"Console - Instrument page"
"31556"	"A-10 PDA"	"Console - Control Menu"
"31557"	"A-10 PDA"	"Console - Configure Menu"
"31558"	"A-10 PDA"	"Console - Maintain Menu"
"31559"	"A-10 PDA"	"Console - Troubleshoot Menu"
"31560"	"A-10 PDA"	"Console - Help Menu"
"31562"	"A-10 PDA"	"Method Editor"
"31563"	"A-10 PDA"	"Acquisition"
"31564"	"A-10 PDA"	"Reporting"
"31565"	"A-10 PDA"	"Error Reporting"
"31566"	"A-10 PDA"	"On Line Help"
"31567"	"A-10 PDA"	"Firmware"
"31873"	"A-10 PDA"	"Installer"
"31814"	"A-10 RI"	"Firmware"
"31976"	"A-10 RI"	"Front Panel"
"31977"	"A-10 RI"	"Naming"
"31978"	"A-10 RI"	"Instrument Control Panel"
"31979"	"A-10 RI"	"Console - System Page"
"31980"	"A-10 RI"	"Console - Instrument Page"
"31981"	"A-10 RI"	"Console - Control Menu"

"31982"	"A-10 RI"	"Console - Configure Menu"
"31983"	"A-10 RI"	"Console - Maintain Menu"
"31984"	"A-10 RI"	"Console Troubleshoot menu"
"31985"	"A-10 RI"	"Console - Help Menu"
"31986"	"A-10 RI"	"Method Editor"
"31987"	"A-10 RI"	"Acquisition"
"31988"	"A-10 RI"	"Reporting"
"31989"	"A-10 RI"	"Error Reporting"
"31990"	"A-10 RI"	"Online Help"
"31992"	"A-10 RI"	"Installer"
"32090"	"A-10 RI"	"Startup and Shutdown"
"31568"	"A-10 SSM"	"Firmware"
"31871"	"A-10 SSM"	"Installer"
"31533"	"A-10 UV"	"Startup and Shutdown"
"31534"	"A-10 UV"	"Front Panel"
"31535"	"A-10 UV"	"Naming"
"31536"	"A-10 UV"	"Instrument Control Panel"
"31537"	"A-10 UV"	"Console System Page"
"31538"	"A-10 UV"	"Console Insstrument Page"
"31539"	"A-10 UV"	"Console - Control Menu"
"31540"	"A-10 UV"	"Console Configure Menu"
"31541"	"A-10 UV"	"Console Maintain Menu"
"31542"	"A-10 UV"	"Console - Troubleshoot Menu"
"31543"	"A-10 UV"	"Console - Help Menu"
"31544"	"A-10 UV"	"Method Editor"
"31545"	"A-10 UV"	"Acquisition"
"31546"	"A-10 UV"	"Reporting"
"31547"	"A-10 UV"	"Error Reporting"
"31548"	"A-10 UV"	"Online Help"
"31549"	"A-10 UV"	"Firmware"
"31872"	"A-10 UV"	"Installer"

Resolved SCRs

"Id"	"Primary Product"	"Title"
"32894"	"A-10 PDA"	"A10-PDA Fix Help Links issues pre-TCR"
"32916"	"A-10 PDA"	"A-10 PDA Databuffer overrun alarm from Status"
"32776"	"A-10 UV"	"A-10 UV Errors keep System Status Green on console"
"32528"	"Console"	"Console Plots adding un-selected plot after closing/reopening"