



Altus A-30 System Software Release Notes

Release #015, 27 April 2015

Contents:

The following instruments and/or projects are included in this release:

A-30 Module Name	Instrument Type Name	ICS Version	Firmware Version	Checksum
A-30 Solvent Delivery Module	A30-SDM	1.00.5203	1.0	0xAF7D56F2
A-30 Sampling Module	A30-SM	1.00.5214	1.0	0x347501c6
A-30 UV Detector	A30-UV	1.00.5209	1.0	d72fa36a
A-30 PDA Detector	A30-PDA	1.00.5205	1.0	0xdc43ad9b
A-30 RI Detector	A30-RI	1.00.5177	1.0	aa0be474
A-30 Column Module	A30-CM	1.00.5175	1.0	0x18c39c8b
A-30 FL Detector	A30-FL	1.00.5184	1.0	0xCCF5960E

NOTES:

Firmware – All instruments must be updated with the new firmware using Autoloader

A-30 Instruments require a common CPU board which is version 2.0 or greater. A problem specific to internal development / evaluation when attempting to use older Waters variants of these similar based products.

Verified TCRs – All of the TCRs have been completed.

Resolved SCR:

"Id"	"Title"	"Primary Product"
"33280"	"online help link from Console logs doesn't display specific help topic"	"A-30 SDM"
"33164"	"ICS companion version should be updated"	"Installer"
"33313"	"MAKO: Verify Files Waters.Console.PlotViewer.exe not found error"	"Installer"
"33184"	"MAKO SYNC: solvent name <not found> (SCR#32404)"	"N/A"