



Empower Software Installation Qualification

Database Service: Romm58

Project Name: Valid_OQ1

Software Qualification for Node: Romm58

Node Information

Owner	System
Node Name	Romm58
Node Type	Empower
Access	OwnerGroupWorld
Node Comments	
Share Systems	Yes
Password Required	No
Time Zone	US/Eastern
Number of Node Info Invalid Password Attempts	0
Setup Version	3471
Service Packs	Service Release 1;Feature Release 1;Feature Release 2;
Install Type	Standalone
Time Zone Update	2

IQ Status

IQ Status	Pass
IQ Date	29 April 2013
IQ Comment	NA RMS 29 April 2013

OQ Status

OQ Status	Pass
OQ Date	29 April 2013
OQ Comment	NA RMS 29 April 2013
OQ MMM Status	Pass
OQ MMM Date	29 April 2013
OQ MMM Comment	NA RMS 29 April 2013

Computer Components

Equipment Name	Workstation	Installation Start Date	29 April 2013
CPU Serial Number or Owner ID	L021308	Location	BLd A pole C24
Manufacturer	lenovo		
Model	M58		
OS Name and Revision Number	A		
Purchase Order Number	45000012345		

Documentation Information

Release Notes Received	Yes
Release Notes Revision	A
Received Empower Documentation CD	Yes
Documentation Comments	NA

Configuring Components and Peripherals

Configured at Factory	Yes
Configured on Site	No
Acquisition Device	N/A
Peripheral Devices	N/A

IEEE-488 Devices	N/A
RS-232 Serial Devices	N/A
8-Port Serial Card	N/A
Acquisition Devices	N/A
Configuring Computer and Peripherals Comments	NA

Verify Files Summary Information

Installation Information.

Current Date and Time - Monday, April 29, 2013 13:52:27
Computer Name - Romm68
Installation Type - Personal
S/W Version - Empower 3 Software Build 3471
Registered User - Romuald
Company Name - Waters
Support Plan ID - xxxxxxxxx
Operating System Name - Windows 7 Professional
Operating System Version - 6.1
Operating System Upgrades - Service Pack 1

ICS Version - Installed ICS Component

1.40.1882 - 2420 Evaporative Light Scattering Detector
1.40.1882 - 2424 ELS Detector
1.50.1521 - ACQUITY Binary Solvent Manager
1.50.1678 - ACQUITY Column Manager
- Waters ELS Detector
1.40.2407 - Acquity FLR Detector
1.50.1121 - ACQUITY PDA Detector
1.50.1621 - ACQUITY Quaternary Solvent Manager
1.50.2736 - ACQUITY Sample Manager
1.50.1481 - ACQUITY Sample Manager FTN
1.50.2530 - ACQUITY TUV Detector
1.51.3230 - ACQUITY UPLC Local Console Controller
2.1.0.0 - Agilent LC
1.06.1007 - Agilent LC Control Software
1.31.2201 - Waters 2489
1.30.1166 - Waters 2998 PDA Detector
1.30.12.1107 - Waters A6850 Software
2.5.12.0210 - Waters A7890 Software
1.40.1882 - Waters ELS Detector
1.30.1023.1 - Waters eSATIN Software
1.41.2336 - Waters TQ Detector

The following product updates have been applied to this installation:

Service Release 1
Feature Release 1
Feature Release 2

Database Installation Verification Utility.

Database Alias - Local
of Installed Named User License(s)-10000
of Installed System License(s)-100
Database Version - 7.20.00.15
Oracle Version - 11.2.0.2.0

Installed Oracle - Empower

Installed Empower 3 License: (Please fill in Serial Number if absent)

Database Verification Complete.

Waters Installation Qualification - Summary

No Installation changes were detected.

This qualifies your software installation on this node.

SQT Sign off Table

	Sample Name	Result Id	Sign Off Full Name	Sign Off Reason	Sign Off Date	Sign Off ID	Sign Off Method Name
1	PQ Unk. 1	3031	Sandra McSweeney (Sandra)	Sign Off Level 2, Reason: Approval	4/29/2013 2:26:31 PM EDT	3265	IQ All Node
2	PQ Unk. 1	3031	Romuald Mc Sweeney (Romuald)	Sign Off Level 1, Reason: Review	4/29/2013 2:22:31 PM EDT	3264	IQ Single Node

SQT Sign off Table

	Sign Off Method Id	Sign Off Method Version
1	3160	10
2	3162	4