



To Measure High Frequencies:
1. Connect signal to GPCTR1_SOURCE.
2. Connect gating signal to GPCTR0_GATE (Optional).





Input	Input	Input	Input	xxxxx	Input	Input	Output
Fixture closed Active low	ID bit2 2475	ID bit1 2414	ID bit0 2487	spare	Latch 2 Active low	Latch 1 Active low	latch reset
MSB							LSB