

From: [Joel Mamalateo Deduyo](#)
To: [Siddharth Udayshankar](#); [Ops_Wppl_Support](#); [HuaZhen Luo](#)
Cc: [Nallajanula Phani Bhushan](#); [Niu Niu](#); [Amy Xu Xia Jie](#); [Gary Lai Yam Bee](#); [Aldwin Pilapil](#); [Kim Seng Chua](#); [Nallajanula Phani Bhushan](#); [Pratheush Paleri](#); [Mohammad Shamsul Bin Afandi](#); [Kee David](#); [Bernard Retutas Pamplona](#); [Vincent Lim](#)
Subject: [EXT] OESR 289002227 Small Shunt Broken PN 400001784 Baffle, Flow Cell
Date: Monday, 14 September, 2020 17:39:05
Attachments: [image002.png](#)
[289002227RevB.pdf](#)
[OESR 289002227 Small Shunt Broken 400001784 BAFFLE, FLOW CELL.docx](#)
[279003847 ASP rev B.pdf](#)

ATTENTION: This email originated from outside of the organization. Please do not open any attachments or click any links unless you recognize the sender and know the content is safe.

Hi Ops_Support,

Pls. refer to below:

1. Problem Statement.

- Not able to perform 289003847 step 8.16 onwards. Tester unable to print out test report.

Unable to perform Oper 3.6

2. Acceptance criteria that is not met. (e.g. relevant specification number and revision)

- OB shall pass complete test as per ASP 289003847.

3. Relevant records (e.g. Incoming QA, Test Records, Photos, trackise NCRs numbers and related issue)

- refer to below photo.



4. Info on whether this issue impacts revenue.

- May impact revenue if not able to recover tester in time.

Note:

We applied glue to make it work but its best if we can get a new SMALL Shunt PN 289002227

Best Regards,

flex

Joel Mamalateo Deduyo

Senior Test Engineer

1 Kallang Place

Singapore 339211

direct: +65 6507 5982

mobile: +65 9685 8678

email: JoelMamalateo.Deduyo@flex.com

web: flex.com

Legal Disclaimer :

The information contained in this message may be privileged and confidential. It is intended to be read only by the individual or entity to whom it is addressed or by their designee. If the reader of this message is not the intended recipient, you are on notice that any distribution of this message, in any form, is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete or destroy any copy of this message!