

Spare Parts used in Waters@Kallang Place

Feb 2020 Calibration

SUM	\$ 215.06
COA	\$ 21.51
Total sum	\$ 236.57

S/N	Date	DESCRIPTION	Part no	BAAN No.	Quantity	Cost (US\$)/EA	Remarks
1	14-Feb-20	ASSY, PCB, 2489 TUV PERSONALITY	WAT-210000355	WAT-210000355	1	\$215.06	For repair of golden unit s/n:L0787E095M due to tester keep on restarting.