

Spare Parts used in Waters@Kallang Place

Mar 2020 Calibration

SUM	\$ 718.57
COA	\$ 71.86
Total sum	\$ 790.43

S/N	Date	DESCRIPTION	Part no	Quantity	Cost (US\$)/EA	Remarks
1	20-Mar-20	PWR SUP DC 80W MULTI-OUTPUT RM	WATH-279003675	2	\$40.00	For 1)TUV detector s/n: M09UPT360A at BSM final test due to lamp lighting failure (faulty) 2)PDA fine align box build fail to power up
2	20-Mar-20	POWER SUPPLY, HB LAMP HAMAMATS	WAT-279001105	1	\$101.46	For TUV detector s/n: M09UPT360A at BSM final test due to lamp lighting failure
3	20-Mar-20	ASSEMBLY, CABLE DC PWR SUPPLY	WATH-441001260	1	\$8.76	For TUV detector s/n: M09UPT360A at BSM final test due to lamp lighting failure (burnt mark)
4	20.Mar.20	ASSY, HB DEUTERIUM LAMP	WAT-402000351	2	\$154.40	For TUV detector s/n:M09UPT363A and B1587E608A
5	24-Mar-20	INLINE FILTER ASSY	WAT-WAT035190	3	\$13.40	For 1) WPPL and For Actuator Tester TE82800-2 and TE82800-3 as part of maintenance
6	31-Mar-20	POWER SUPPLY 600W TEST	WAT-WAT270471	1	\$179.35	For TE82526-1 due to unable to power up