

Spare Parts used in Waters@Kallang Place

May 2020 Calibration

SUM	\$	526.06
COA	\$	52.61
Total sum	\$	578.67

S/N	Date	DESCRIPTION	Part no	BAAN No.	Quantity	Cost (US\$)/EA	Remarks
1	20-May-20	POWER SUPPLY, HB LAMP HAMAMATS	WAT-279001105	WAT-279001105	1	\$ 101.4600	For 2998 detector(golden unit) p/n: 186299800 s/n: B13998443A due to noise failure.(Spare bench P/n: 700011867)
2	20-May-20	ASSY, PCB 2998 PDA PERSONALITY	WAT-210000404	WAT-210000404	1	\$ 270.9780	For 2998 detector(golden unit) p/n: 186299800 s/n: B13998443A due to noise failure.(Spare bench P/n: 700011867)
3	29-May-20	ASSY, HB DEUTERIUM LAMP	WAT-402000351	WAT-402000351	1	\$ 153.6260	For 2489 box build 186248900 s/n: H1387E731A due to expiry of lamp hours.