

Waters Pacific Pte Ltd

1 Science Park Road, #02-08 The Capricorn, Singapore Science Park II, Singapore 117528

X	Original (please process)
	Confirming (do not duplicate)
X	Quote Attached
Purchase Order Number	
WPPL-OP-021	

Supplier	
Venture International Pte Ltd	
5006 Ang Mo Kio Ave 5, #05-01/12 TECHplace II, Singapore 569873	
Fax Number +65.6368 7617	
Phone:	+65.6732 9898

Requested by:	Luo HuaZhen	Tel	6593.7044
Date:	21.May.20	Mail Stop	
Deliver to:		Ext.	
Department:	WPPL	Mail Stop	
Ship to Location:	1 Science Park Road,#02-08 The Capricorn, Singapore Science Park II, S 117528		

P.O. Date		Delivery Date		Terms	Taxable	Freight		F.O.B		Ship Via	Confirming to	Buyer
21.May.20				30 Days							Jenny	Luo HuaZhen
Item	Qty	U/M	Manufacturer's Part Number	Description				Unit Price	Total Price (USD)	G/L Account Number (Financial Line/Account No.)	CEA Number	
1	1	EA	N/A	Subtotal Calibration Cost (Instrument)				\$ 431.20	\$ 431.20	WP21 615150		
2	1	EA	N/A	Subtotal Calibration Cost (PCBA)					\$ -	WP21 615150		
3	1	EA	N/A	At hoc-Spare and Misc				\$ 637.23	\$ 637.23	WP21 615150		
4												
5												
6				Kindly quote our PO number on all your documents.								
7												
8												
9												
10												
11												
12												
13												
14												
15												
Grand Total - USD									\$1,068.43			

Remarks

Approvals

1.

Edwin Koh, Snr Operations Manager

2

Alan Tan, Snr Finance Manager

Purchasing Copy



Summary	Amount (US\$)	
Calibration \$ to Venture Box Build	USD	-
Calibration \$ to Venture PCBA	USD	431.20
Adhoc cost - spare & misc	USD	637.23
Total	USD	1,068.43

Verified By: [HZ 21 May 2020](#)

External Calibration for Equipment (PCBA)

Q2 2020 (Apr'20)

SUM	USD	392.00
10% Support Cost	USD	39.20
Subtotal	USD	431.20

S/N	Location	Name	Equipment ID	Model	Serial No	Manufacturer	Purpose	Source	CAL DATE	Due	Cycle	Invoice #	Cost USD	COST SGD	Remarks
1	WATERS (PCBA)	Keithley 236 Source Measure unit	PWAT-16GC0027	236	0549819 (ID#95105)	Keithley	Testing Purpose	Keysight	20/04/2020	20/04/2021	12	1148567	USD 392.00	SGD 490.00	

Verified By: HZ 21 May 2020

Miscellaneous Materials
Q2 2020 (Apr'20)

					SUM	USD	142.94		
					10% Support Cost	USD	14.29		
					Subtotal	USD	157.23		
S/N	Part No.	Description	Quantity	Unit Price(S\$)	Unit Price(US\$)	Ext Cost(US\$)	Remarks	Date	
1	279001056	PUMP VACUUM DEGASSER AF	1		USD 142.940	USD 142.940	To replace a faulty part at tester TE82987,approved by HuaZhen as on Tue 4/7/2020 3:50 PM	07.Apr.20	
2									
3									
4									
5									
6									
7									
8									
9									
10									
11									
12									

Verified By: HZ 21 May 2020

Others

Q2 2020 (Apr'20)

Subtotal Others USD 480.00						
S/N	Date	Activity	Quantity	Cost SGD	Cost (US\$)	Remarks
1	23.Apr.20	From Venture to Flex	1	SGD 100.00	USD 80.00	Annual preventive maintenance. 1st pump send out , Serial number: C1525P993A
2	29.Apr.20	From Venture to Flex From Flex to Venture	2	SGD 200.00	USD 160.00	2nd pump (Serial number : C09225P516R) send out & collect back 1st pump
3	05.May.20	From Venture to Flex From Flex to Venture	2	SGD 200.00	USD 160.00	3 rd pump (Serial number: C0925P662R) send out on & collect back 2 nd pump
4	12.May.20	From Flex to Venture	1	SGD 100.00	USD 80.00	Collect back 3 rd pump

Verified By: HZ 21 May 2020



Tax Invoice

Customer Purchase Order Number 4730028588		
Invoice Number 1148567	Invoice Date 05-May-2020	Service Order Number 1-12507910961
Payment Terms NET 30 DAYS		

Attention: Kwang Quek LEE

Bill To:
GES Singapore Pte Ltd
28 Marsiling Ln
GES Bldg
SINGAPORE 739152
Singapore

Attention: Kwang Quek LEE

Ship To:
GES Singapore Pte Ltd
28 Marsiling Ln
GES Bldg
SINGAPORE 739152
Singapore

Please Send Your Remittances To:

SGD: Citibank N.A. Singapore
8 Marina View #16-01 Asia Square Tower 1 Singapore 018960
Acc. No: 0-858158-036 SWIFT Code: CITISGSG
Bank Code / Branch Code: 7214 / 001

Keysight Technologies Singapore (Sales) Pte. Ltd.
No 1 Yishun Ave 7
SINGAPORE 768923
Singapore

Please Direct Inquiries To:

Singapore Customer Contact Center
Telephone: 1800-375 8100/ (65) 6375-8100
Fax: (65) 6755-1214
Email: instruments_services@keysight.com

Keysight Sales Office:

Keysight Technologies Singapore (Sales) Pte Ltd
Company Registration No 201400782D
No 1 Yishun Ave 7
SINGAPORE 768923
Singapore

Item	Product Number/Serial Number Service Description	Service Price	Quantity	Extended Price SGD
1	KEI236/ 0549819 Calibration (non-Keysight product) - Per Incident	490.00	1	490.00
Item Net Total				490.00

Payment is due on 04-Jun-2020	Net Total	490.00
	GST	7.00% 34.30
	Total	SGD 524.30

Comments:

All requests for 3rd party payment must be stated in writing with supporting documents. Keysight reserves sole discretion to accept or reject payment from a third party who is not the Buyer or contractual party.

Tax is calculated based on applicable tax rate in effect today from delivery location(s). Tax rate and taxability of deliverable(s) is subject to change based on prevailing laws. If you dispute the tax rate, please contact your support administrator.

All orders for the sale of Services and spare parts referenced in this Invoice are subject to the then current version of Keysight's Service Terms and Keysight's Terms of Sale with respect to spare parts, and other terms referenced in the Quotation and Service Agreement document. If you have a separate agreement in effect with Keysight covering the sale of Services and spare parts referenced in this Invoice, the terms of that agreement will apply to those Services and spare parts.

HuaZhen Luo

From: HuaZhen Luo
Sent: Tuesday, 7 April, 2020 15:50
To: Myae Soe Chan; Siddharth Udayshankar; Ops_Wppl_Support
Cc: Tan Hong Cheng; Teo Yiek Tiong; Yeehwa Chan
Subject: RE: [EXT] RE: [EXT] OESR - TE82987-1_degasser vacuum pump mulfunction

Hi Chan,

Since you have confirm the degasser vacuum pump is the root cause for failure, please go ahead with replacement.

I will close this OESR since it's a parts replacement request only.

Thank you

Luo HuaZhen
Senior Test Engineer

[T] +65 6593 7044
[F] +65 6873 0820
[W] www.waters.com
[E] huazhen_luo@waters.com



Waters
THE SCIENCE OF
WHAT'S POSSIBLE.™

Waters Pacific Pte Ltd
1 Science Park Road
#02-08 The Capricorn
Singapore Science Park II
Singapore 117528

From: Myae Soe Chan <myaesoe.chan@venture.com.sg>

Sent: Tuesday, 7 April, 2020 14:34

To: Siddharth Udayshankar <Siddharth_Udayshankar@waters.com>; Ops_Wppl_Support <Ops_Wppl_Support@waters.com>

Cc: Tan Hong Cheng <hongcheng_tan@venture.com.sg>; Teo Yiek Tiong <yiektiong_teo@venture.com.sg>; Yeehwa Chan <Yeehwa_Chan@waters.com>

Subject: [EXT] RE: [EXT] OESR - TE82987-1_degasser vacuum pump mulfunction

ATTENTION: This email originated from outside of the organization. Please do not open any attachments or click any links unless you recognize the sender and know the content is safe.

Hi Sidd,
My apologies. Please kindly refer to the attached OESR and reference photo.

Thanks

Best Regards,
Chan

From: Siddharth Udayshankar [mailto:Siddharth_Udayshankar@waters.com]
Sent: Tuesday, April 07, 2020 2:19 PM
To: Myae Soe Chan; Ops_Wppl_Support
Cc: Tan Hong Cheng; Teo Yiek Tiong; Yeehwa Chan
Subject: RE: [EXT] OESR - TE82987-1_degasser vacuum pump malfunction

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Hi Chan,
Please attach the OESR doc.

Thanks
Sid

Siddharth Udayshankar
Product Assurance Engineer

[T] +65 6593 7410
[F] +65 6873 0820
[W] www.waters.com
[E] siddharth_udayshankar@waters.com

Waters
THE SCIENCE OF
WHAT'S POSSIBLE.®

Waters Pacific Pte Ltd
1 Science Park Road
#02-08 The Capricorn
Singapore Science Park II
Singapore 117528

From: Myae Soe Chan <myaesoe.chan@venture.com.sg>
Sent: Tuesday, April 07, 2020 14:17
To: Ops_Wppl_Support <Ops_Wppl_Support@waters.com>

Cc: Tan Hong Cheng <hongcheng_tan@venture.com.sg>; Teo Yiek Tiong <yiektiong_teo@venture.com.sg>; Yeehwa Chan <Yeehwa_Chan@waters.com>

Subject: [EXT] OESR - TE82987-1_degasser vacuum pump mulfunction

ATTENTION: This email originated from outside of the organization. Please do not open any attachments or click any links unless you recognize the sender and know the content is safe.

Hi Sidd,

I would like to raise the attached request due to the degasser hardware error at TE82987.

As per troubleshooting, it is due to the degasser vacuum pump(P/N: 279001056).

No	Part Number	Description	Qty	Unit Price	Remark/Reason
1	279001056	Degasser Vacuum Pump AF	1	142.94	To replace faulty part at TE82987-1. Error message is "degasser HW error" and pressure is -0.1psi

Hi Hua Zhen,

As communicated, please kindly refer to the attached request.

Thank you

Best Regards,

Chan

Confidential/Privileged information may be contained in this email. If you are not the intended recipient, please do not copy, distribute or use it for any purpose, nor disclose its contents to any other person. Please notify the sender immediately if you receive this in error.

The information in this email is confidential, and is intended solely for the addressee(s). Access to this email by anyone else is unauthorized and therefore prohibited. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited and may be unlawful.

Confidential/Privileged information may be contained in this email. If you are not the intended recipient, please do not copy, distribute or use it for any purpose, nor disclose its contents to any other person. Please notify the sender immediately if you receive this in error.