



Tektronix Southeast Asia Pte Ltd
Co Reg No. 199202303Z
No 1 Clementi Loop
06-02
129808 Singapore
Phone: 6563563900
Fax: 6563564483
Carolyn Ang
Phone: 604-643-9679

SERVICE QUOTATION

Issue Date: 23-Apr-2020
Quotation Number: 2001050
Valid: 30 days
Payment Terms: Net 30
Your reference: 707A12141

Bill To:

Flextronics Shah Alam Sdn Bhd (206755-A)
C/ O FLEXTRONICS TECHNOLOGIES (I) PVT LTD
Global shared services
7TH FLOOR, CAMPUS II, NO. 143, DR. MGR ROAD
MILLENNIA BUSINESS PARK
600096 INDIA

Agreement: Tektronix Terms and Conditions

Deliver To:

Flextronics Shah Alam Sdn Bhd (206755-A)
PLO 226, Kawasan Perindustrian,
Jalan Cyber 1, Kawasan Perindustrian Senai III,
SENAI
81400 MALAYSIA

To: Wafa Huwaina binti Abd Majid

Phone: 07 597 2811

E-Mail: WafaHuwainaBinti.AbdMajid@flex.com

Thank you for asking us to maintain the instrument(s) listed below. Please refer to the attached explanation of charges.
To accept this quotation, a method of payment is required prior to initiation of service. Contact us with your purchase order to initiate the service quoted.

Please reference your quote number on all other communications and send PO to : service.asean@tektronix.com

Accepted by:

Name, Company Stamp and Date

Line	Model	Serial No	Manufacturer	Description	Type of Service:	As listed below	Standard Price	Extended (SGD)
1	236	0810603	KEITHLEY, INC.	SOURCE MEASURE UNIT				
				GST			330.05	330.05 ☐
				REPAIR WITH APPROPRIATE			4,190.00	4,190.00 ☐
				CERTIFICATION STD PRICE				
				Test Data (THIS IS AN OPTIONAL			225.00	225.00 ☐
				EXTRA)				
				FREIGHT			300.00	300.00 ☐

Received**Customer Comments:****Type of Service:****Type of Service:****Quote Comments:****Quote Comments:****Quote Comments:****Quote Comments:**

Issue: unit failed voltage source and measure verification, failed at current source (1mA to 100mA range, 1nA to 100uA range).

F: Standard Price Repair

F: Standard Price Calibration Data

Service Location: Tektronix Solon, Ohio

Freight charges = 1 way International return to Senai, Johor.

Model 236 has end of full support since 2008, currently is BEST EFFORT REPAIR subjected to worldwide spare parts availability.

If unit is not repairable, an evaluation fees of SGD 1,200/- and Freight Charge SGD \$300 applies.

Line Total: (SGD) 5,045.05 5,045.05 ☐