


ICT Fixture - ID# 9046-11

ICT Fixture



ICT test fail Y1 frequency measurement.
Frequency measured 0 Mhz



Y1
12MHz FREQUENCY TEST FAILED.
FREQUENCY WAS 0MHz.
P/N = 290230

U11
(MC68HC11)
P/N = 290130, X/Y 3.5/3.25, Sheet 126
Mail 339; Pin 5; Mode: N&I

26-DEC-18 10:07:00
BOARD 9406-11 FAILED

SER # 171218120M

Suspect reject is due to the fixture internal hardware (Testware Frequency Board) faulty

```

/*****
/*          Frequency Tests          */
/*          -----          */
/*
/* Y1 (12Mhz) will be tested using a Testware Frequency Board. The */
/* measurement will be made on the opposite side of L3, so a */
/* more accurate reading can be made. */
/* */
/*****/

```

