

Waters Pacific Pte Ltd

1 Science Park Road, #02-08 The Capricorn, Singapore Science Park II, Singapore 117528

X	Original (please process)
	Confirming (do not duplicate)
X	Quote Attached
Purchase Order Number	
WPPL-OP-42 WPPL-OP-041	

Supplier	
Venture International Pte Ltd	
5006 Ang Mo Kio Ave 5, #05-01/12 TECHplace II, Singapore 569873	
Fax Number +65.6368 7617	
Phone:	+65.6732 9898

Requested by:	Luo HuaZhen	Tel	6593.7044
Date:	24.Aug.20	Mail Stop	
Deliver to:		Ext.	
Department:	WPPL	Mail Stop	
Ship to Location:	1 Science Park Road,#02-08 The Capricorn, Singapore Science Park II, S 117528		

P.O. Date		Delivery Date		Terms	Taxable	Freight		F.O.B		Ship Via	Confirming to	Buyer
24.Aug.20				30 Days							Jenny	Luo HuaZhen
Item	Qty	U/M	Manufacturer's Part Number	Description				Unit Price	Total Price (USD)	G/L Account Number (Financial Line/Account No.)	CEA Number	
1	1	EA	N/A	Venture Jul20 Calibration Claim - Ad hoc-spare and Misc				\$ 462.88	\$ 462.88	WP21 615150		
2												
3												
4												
5												
6				Kindly quote our PO number on all your documents.								
7												
8												
9												
10												
11												
12												
13												
14												
15												
Grand Total - USD									\$462.88			

Remarks

Approvals

1.

Edwin

25th Aug 2020

2. Alan Tan, Snr Finance Manager

Purchasing Copy



Summary	Amount (US\$)	
Calibration \$ to Venture Box Build	USD	-
Calibration \$ to Venture PCBA	USD	-
Adhoc cost - spare & misc	USD	462.88
Total	USD	462.88

Verified By: HZ 24 Aug 2020

External Calibration for Equipment used in Waters@Venture
July 2020 External Calibration

Sum	USD 0.00
10% Support Cost	\$ -
Subtotal Cost External Cal	\$ -

EQID	OWNER	EQUIPMENT	MANUFACTURER	MODEL	SERIAL NO.	CAL INTERVAL	PO	Cost USD	COST SGD	VENDOR	Cal Report	Vendor Cert	Vendor Invoice	Remarks
NA	Ricky Celis Cortez	20 MHZ FUNCTION/ARBITRARY WAVEFORM GENERATOR	AGILENT	33220A	MY44015802	12 Months	NA	NA	NA	Micro Precision	 WATERS (PCBA)_2020_JULY_MY4	 D:\My Documents\Documents\Micro Precision Cert.pdf	NA	Customer Paid
93467	Chua Chong Keong	Electrical Safety Analyzer	Chroma	19032	19032G400264 (ID#93467)	12 Months	NA	NA	NA	Micro Precision	 WATERS (SMU)_2020_JULY_1903	 D:\My Documents\Documents\Micro Precision Cert.pdf	NA	Customer Paid
90966	Myae Soe Chan	Digital Gram Balance - WP07 (Weighing Scale)	AND (HR-200)	HR-200	12316088 (90966)	6 Months	NA	NA	NA	Micro Precision	 WATERS (SMU)_2020_JULY_12316088.pdf	 D:\My Documents\Documents\Micro Precision Cert.pdf	NA	Customer Paid
94322	Myae Soe Chan	Digital Gram Balance - WP07 (Weighing Scale)	AND (HR-200)	HR-200	12336767(94322)	6 Months	NA	NA	NA	Micro Precision	 WATERS (SMU)_2020_JULY_12336767.pdf	 D:\My Documents\Documents\Micro Precision Cert.pdf	NA	Customer Paid

Verified By: HZ 24 Aug 2020

Miscellaneous Materials

Q3 2020 (July'20)

SUM	USD	420.80
10% Support Cost	USD	42.08
Subtotal	USD	462.88

S/N	Part No.	Description	Quantity	Unit Price(S\$)	Unit Price(US\$)	Ext Cost(US\$)	Remarks	Date
1	205001476	(279002426) 10PK ASSY VALVE VENT 18	1		USD 420.800	USD 420.800	Tester Replacement, approved by HuaZhen as on Wednesday, 8 July 2020 9:48 am	15.Jul.20
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								

Verified By: HZ 24 Aug 2020

Ei Lwin Htay

From: HuaZhen Luo <HuaZhen_Luo@waters.com>
Sent: Wednesday, 8 July 2020 9:48 am
To: EiLwin.Htay; Ops_Wppl_Support
Cc: Teo Yiek Tiong; Chua Chong Keong
Subject: RE: [EXT] OESR - Dynamic Leak at FTN tester TE83064-16

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Hi Lwin,

As per discussion, please go ahead with replacement and I will close this OESR as it's fixed.

Luo HuaZhen
Senior Test Engineer

[T] +65 6593 7044
[F] +65 6873 0820
[W] www.waters.com
[E] huazhen_luo@waters.com



Waters

THE SCIENCE OF
WHAT'S POSSIBLE.™

Waters Pacific Pte Ltd
1 Science Park Road
#02-08 The Capricorn
Singapore Science Park II
Singapore 117528

From: Ei Lwin Htay <eilwin.htay@venture.com.sg>
Sent: Monday, 6 July, 2020 15:30
To: Ops_Wppl_Support <Ops_Wppl_Support@waters.com>
Cc: Teo Yiek Tiong <yiektiong_teo@venture.com.sg>; HuaZhen Luo <HuaZhen_Luo@waters.com>; Chua Chong Keong <chongkeong.chua@venture.com.sg>
Subject: [EXT] OESR - Dynamic Leak at FTN tester TE83064-16

ATTENTION: This email originated from outside of the organization. Please do not open any attachments or click any links unless you recognize the sender and know the content is safe.

Hi All,

FTN tester TE83064-16 had Dynamic leak issue in last week, 01 July.

After troubleshooting, it is found that leakage at vent valve of BSM module of the tester.

After changing, failure was resolved and functional verification was performed for both I class and H class.

Thank you.

Regards,
Lwin

Confidential/Privileged information may be contained in this email. If you are not the intended recipient, please do not copy, distribute or use it for any purpose, nor disclose its contents to any other person. Please notify the sender immediately if you receive this in error.

The information in this email is confidential, and is intended solely for the addressee(s). Access to this email by anyone else is unauthorized and therefore prohibited. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited and may be unlawful.