

Waters Pacific Pte Ltd

1 Science Park Road, #02-08 The Capricorn, Singapore Science Park II, Singapore 117528

X	Original (please process)
	Confirming (do not duplicate)
X	Quote Attached
Purchase Order Number	
WPPL-OP-020	

Supplier	
Flex	
1 Kallang Pl, Singapore 339211	
Fax Number +65.6842.3739	
Phone:	+65.6507.6507

Requested by:	Luo HuaZhen	Tel	6593.7044
Date:	01.Feb.21	Mail Stop	
Deliver to:		Ext.	
Department:	WPPL	Mail Stop	
Ship to Location:	1 Science Park Road,#02-08 The Capricorn, Singapore Science Park II, S 117528		

P.O. Date		Delivery Date		Terms	Taxable	Freight		F.O.B		Ship Via	Confirming to	Buyer
01.Feb.21				30 Days							Niu Niu	Luo HuaZhen
Item	Qty	U/M	Manufacturer's Part Number	Description				Unit Price	Total Price (USD)	G/L Account Number (Financial Line/Account No.)	CEA Number	
1	1	EA	N/A	Cost to rework 6units of 186248900 from reliability test to be used for Alliance final tester, including Labor and material costs.				\$ 2,023.67	\$ 2,023.67	WP21 170100	WPPL19022	
2												
3												
4												
5												
6				Kindly quote our PO number on all your documents.								
7												
8												
9												
10												
11												
12												
13												
14												
15												
Grand Total - USD									\$2,023.67			

Remarks

This 6 units of TUV 186248900 rework is to refurbish TUV detectors from Project- mirror realibility test.

The refurbished TUV will be re-used for Alliance Final Test Stations upgrade under CEA WPPL19022.

Please refer to attached email communciation for details.

Approvals

1. Edwin Koh 01 Feb 2021

Edwin Koh, Snr Operations Manager

2. Alan Tan

Alan Tan, Snr Finance Manager

Purchasing Copy

From: [Alan Tan](#)
To: [Edwin Koh](#); [HuaZhen Luo](#)
Cc: [Sue Jin Ng](#); [Christine Zhao](#); [WanLi Yee](#)
Subject: RE: Cost to rework 6units of 2489 Detector from reliability test
Date: Monday, 1 February, 2021 20:22:22
Attachments: [image004.png](#)
[image006.png](#)
[image007.png](#)
[image009.png](#)
[image010.png](#)
[image011.png](#)
[image012.png](#)
[image013.png](#)
[image015.png](#)

Approved
rdgs

From: Edwin Koh <Edwin_Koh@waters.com>
Sent: Monday, 1 February, 2021 19:56
To: HuaZhen Luo <HuaZhen_Luo@waters.com>
Cc: Alan Tan <Alan_Tan@waters.com>; Sue Jin Ng <Sue_Jin_Ng@waters.com>; Christine Zhao <Christine_Zhao@waters.com>; WanLi Yee <WanLi_Yee@waters.com>
Subject: RE: Cost to rework 6units of 2489 Detector from reliability test

Hi Huazhen,

Approved per request

Thanks
Edwin

From: HuaZhen Luo <HuaZhen_Luo@waters.com>
Sent: Monday, February 1, 2021 18:00
To: Edwin Koh <Edwin_Koh@waters.com>
Cc: Alan Tan <Alan_Tan@waters.com>; Sue Jin Ng <Sue_Jin_Ng@waters.com>; Christine Zhao <Christine_Zhao@waters.com>; WanLi Yee <WanLi_Yee@waters.com>
Subject: FW: Cost to rework 6units of 2489 Detector from reliability test

Hi Edwin,

Please kindly review and approve this rework of 6x TUV units from reliability test under CEA WPPL19022. Adding PO from Flex in attachment for your reference.

Thank you

Luo HuaZhen
Senior Test Engineer

[T] +65 6593 7044
[F] +65 6873 0820
[W] www.waters.com
[E] huazhen_luo@waters.com



Waters
THE SCIENCE OF
WHAT'S POSSIBLE.™

Waters Pacific Pte Ltd
1 Science Park Road
#02-08 The Capricorn
Singapore Science Park II
Singapore 117528

From: Niu Niu <niu.niu@flex.com>
Sent: Thursday, 28 January, 2021 19:32
To: HuaZhen Luo <HuaZhen_Luo@waters.com>
Cc: Joel Mamalateo Deduyo <joelmamalateo.deduyo@flex.com>; Desmond Ann <Desmond_Ann@waters.com>; Aldwin Pilapil <aldwin.pilapil@flex.com>; Gary Lai Yam Bee <yambeegary.lai@flex.com>; Edwin Koh <Edwin_Koh@waters.com>; Nallajanula Phani Bhushan <phanibhushan.nallajanula@flex.com>
Subject: [EXT] Cost to rework 6units of 2489 Detector from reliability test

ATTENTION: This email originated from outside of the organization. Please do not open any attachments or click any links unless you recognize the sender and know the content is safe.

Hi Hua Zhen,

Attached is quotation to rework 6units of 2489 Detectors from reliability test.

Sure, we will start to rework after we receive your PO.

Thank you.

Regards,
Niu Niu

From: HuaZhen Luo <HuaZhen_Luo@waters.com>
Sent: Thursday, January 28, 2021 8:56 AM
To: Joel Mamalateo Deduyo <joelmamalateo.deduyo@flex.com>; Niu Niu <niu.niu@flex.com>; Desmond Ann <Desmond_Ann@waters.com>; Aldwin Pilapil <aldwin.pilapil@flex.com>; Gary Lai Yam Bee <yambeegary.lai@flex.com>
Cc: Edwin Koh <Edwin_Koh@waters.com>; Nallajanula Phani Bhushan <phanibhushan.nallajanula@flex.com>
Subject: RE: Weekly Engineering Meeting (05 Aug 2020) - rework 4units of 2489 Detector from reliability test

Hi Niu Niu/Joel,

Please kindly send us quotation for remaining 6 units 2489 Detector rework, and arrange rework for these 6 units.
I will send PO to you once having your quotation. Thank you

Luo HuaZhen
Senior Test Engineer

[T] +65 6593 7044
[F] +65 6873 0820
[W] www.waters.com
[E] huazhen_luo@waters.com



Waters
THE SCIENCE OF
WHAT'S POSSIBLE.™

Waters Pacific Pte Ltd
1 Science Park Road
#02-08 The Capricorn
Singapore Science Park II
Singapore 117528

From: Joel Mamalateo Deduyo <joelmamalateo.deduyo@flex.com>
Sent: Tuesday, 15 September, 2020 09:17
To: HuaZhen Luo <HuaZhen_Luo@waters.com>; Niu Niu <niu.niu@flex.com>; Desmond Ann <Desmond_Ann@waters.com>; Aldwin Pilapil <aldwin.pilapil@flex.com>; Gary Lai Yam Bee <yambeegary.lai@flex.com>
Cc: Edwin Koh <Edwin_Koh@waters.com>; Nallajanula Phani Bhushan <phanibhushan.nallajanula@flex.com>
Subject: [EXT] RE: Weekly Engineering Meeting (05 Aug 2020) - rework 4units of 2489 Detector from reliability test

ATTENTION: This email originated from outside of the organization. Please do not open any attachments or click any links unless you recognize the sender and know the content is safe.

Hi Hua Zhen,

This activity is completed (4 units rework for 2489 units), pls .advise if you want o ship on your side ?

Best Regards,

flex

Joel Mamalateo Deduyo
Senior Test Engineer

1 Kallang Place
Singapore 339211
direct: +65 6507 5982
mobile: +65 9685 8678
email: JoelMamalateo.Deduyo@flex.com
web: flex.com

From: HuaZhen Luo <HuaZhen_Luo@waters.com>
Sent: Tuesday, September 15, 2020 9:14 AM
To: Niu Niu <niu.niu@flex.com>; Desmond Ann <Desmond_Ann@waters.com>; Joel Mamalateo Deduyo <joelmamalateo.deduyo@flex.com>; Aldwin Pilapil <aldwin.pilapil@flex.com>; Gary Lai Yam Bee <yambeegary.lai@flex.com>
Cc: Edwin Koh <Edwin_Koh@waters.com>; Nallajanula Phani Bhushan <phanibhushan.nallajanula@flex.com>
Subject: RE: Weekly Engineering Meeting (05 Aug 2020) - rework 4units of 2489 Detector from reliability test

Hi Joel/Niu Niu,

Is this rework done?
Please kindly update the status. Thanks

Luo HuaZhen
Senior Test Engineer

Waters
THE SCIENCE OF
WHAT'S POSSIBLE.™

[T] +65 6593 7044
[F] +65 6873 0820
[W] www.waters.com
[E] huazhen_luo@waters.com

Waters Pacific Pte Ltd
1 Science Park Road
#02-08 The Capricorn
Singapore Science Park II
Singapore 117528



From: Niu Niu <niu.niu@flex.com>

Sent: Friday, 28 August, 2020 10:35

To: HuaZhen Luo <HuaZhen_Luo@waters.com>; Desmond Ann <Desmond_Ann@waters.com>; Joel Mamalateo Deduyo <joelmamalateo.deduyo@flex.com>; Aldwin Pilapil <aldwin.pilapil@flex.com>; Gary Lai Yam Bee <yambeegary.lai@flex.com>

Cc: Edwin Koh <Edwin_Koh@waters.com>; Nallajanula Phani Bhushan <phanibhushan.nallajanula@flex.com>

Subject: [EXT] RE: Weekly Engineering Meeting (05 Aug 2020) - rework 4units of 2489 Detector from reliability test

ATTENTION: This email originated from outside of the organization. Please do not open any attachments or click any links unless you recognize the sender and know the content is safe.

Hi Hua Zhen,

We received the rework PO.

I've distributed it as required to activate rework.

Joel shall get back to you when rework is done.

Thanks.

Regards,

Niu Niu

From: HuaZhen Luo <HuaZhen_Luo@waters.com>

Sent: Friday, August 28, 2020 10:14 AM

To: Niu Niu <niu.niu@flex.com>; Desmond Ann <Desmond_Ann@waters.com>; Joel Mamalateo Deduyo <joelmamalateo.deduyo@flex.com>; Aldwin Pilapil <aldwin.pilapil@flex.com>; Gary Lai Yam Bee <yambeegary.lai@flex.com>

Cc: Edwin Koh <Edwin_Koh@waters.com>; Nallajanula Phani Bhushan <phanibhushan.nallajanula@flex.com>

Subject: RE: Weekly Engineering Meeting (05 Aug 2020) - rework 4units of 2489 Detector from reliability test

Hi Niu Niu,

The attached is PO with approval for this rework.

Please kindly update us once the rework is done and TUV detectors are ready for use in Alliance final tester upgrade.

Thanks

Luo HuaZhen
Senior Test Engineer

[T] +65 6593 7044
[F] +65 6873 0820
[W] www.waters.com
[E] huazhen_luo@waters.com



Waters
THE SCIENCE OF
WHAT'S POSSIBLE.™

Waters Pacific Pte Ltd
1 Science Park Road
#02-08 The Capricorn
Singapore Science Park II
Singapore 117528

From: Niu Niu <niu.niu@flex.com>

Sent: Monday, 17 August, 2020 16:25

To: HuaZhen Luo <HuaZhen_Luo@waters.com>; Desmond Ann <Desmond_Ann@waters.com>; Joel Mamalateo Deduyo <joelmamalateo.deduyo@flex.com>; Aldwin Pilapil <aldwin.pilapil@flex.com>; Gary Lai Yam Bee <yambeegary.lai@flex.com>

Cc: Edwin Koh <Edwin_Koh@waters.com>; Nallajanula Phani Bhushan <phanibhushan.nallajanula@flex.com>

Subject: [EXT] RE: Weekly Engineering Meeting (05 Aug 2020) - rework 4units of 2489 Detector from reliability test

ATTENTION: This email originated from outside of the organization. Please do not open any attachments or click any links unless you recognize the sender and know the content is safe.

Hi Hua Zhen,

Please see attached cost to rework 4units.

Materials to be used:

--	--	--	--	--

S/n	Part number	Part Description	Qty
1	402000170	MIRROR, 3X ELLIPSOIDAL DT	1
2	402000351	ASSY, HB DEUTERIUM LAMP	1

Regards,
Niu Niu

From: HuaZhen Luo <HuaZhen_Luo@waters.com>
Sent: Monday, August 17, 2020 3:45 PM
To: Desmond Ann <Desmond_Ann@waters.com>; Joel Mamalateo Deduyo <joelmamalateo.deduyo@flex.com>; Aldwin Pilapil <aldwin.pilapil@flex.com>; Gary Lai Yam Bee <yambeegary.lai@flex.com>; Niu Niu <niu.niu@flex.com>
Cc: Edwin Koh <Edwin_Koh@waters.com>; Nallajanula Phani Bhushan <phanibhushan.nallajanula@flex.com>
Subject: RE: Weekly Engineering Meeting (05 Aug 2020)

Hi Joel/NiuNiu,

Please kindly send me the quotation for 4x TUV rework as per discussion. So that we can prepare the PO for this rework.
Thank you

Luo HuaZhen
Senior Test Engineer

[T] +65 6593 7044
[F] +65 6873 0820
[W] www.waters.com
[E] huazhen_luo@waters.com



Waters
THE SCIENCE OF
WHAT'S POSSIBLE.™

Waters Pacific Pte Ltd
1 Science Park Road
#02-08 The Capricorn
Singapore Science Park II
Singapore 117528

From: HuaZhen Luo
Sent: Friday, 7 August, 2020 10:36
To: Desmond Ann <Desmond_Ann@waters.com>; Joel Mamalateo Deduyo <joelmamalateo.deduyo@flex.com>; Aldwin Pilapil <aldwin.pilapil@flex.com>; Gary Lai Yam Bee <yambeegary.lai@flex.com>; Niu Niu <niu.niu@flex.com>
Cc: Edwin Koh <Edwin_Koh@waters.com>; Nallajanula Phani Bhushan <phanibhushan.nallajanula@flex.com>
Subject: RE: Weekly Engineering Meeting (05 Aug 2020)

Hi Desmond/NiuNiu/Joel,

We're working with Milford on Alliance Final Testers upgrade.
Currently we're in progress to upgrade 4x stations. Therefore we're only need 4x TUV rework quote and advise rework time. So to get ready for the upcoming upgrade kit.
The rest of units may reserve for future upgrade if these 4x stations upgrade are working as expected.
Hope above is clear to team, let's discuss if you have any other questions. Thanks

Luo HuaZhen
Senior Test Engineer

[T] +65 6593 7044
[F] +65 6873 0820
[W] www.waters.com
[E] huazhen_luo@waters.com



Waters
THE SCIENCE OF
WHAT'S POSSIBLE.™

Waters Pacific Pte Ltd
1 Science Park Road
#02-08 The Capricorn
Singapore Science Park II
Singapore 117528

From: Desmond Ann <Desmond_Ann@waters.com>
Sent: Friday, 7 August, 2020 08:58
To: Joel Mamalateo Deduyo <joelmamalateo.deduyo@flex.com>; HuaZhen Luo <HuaZhen_Luo@waters.com>; Aldwin Pilapil <aldwin.pilapil@flex.com>; Gary Lai Yam Bee <yambeegary.lai@flex.com>
Cc: Edwin Koh <Edwin_Koh@waters.com>; Nallajanula Phani Bhushan <phanibhushan.nallajanula@flex.com>
Subject: RE: Weekly Engineering Meeting (05 Aug 2020)

Hi Edwin,

You can share your thoughts on this?

Regards,

Desmond.

Desmond Ann
Team Lead, Manufacturing



[T] +65 6593 7082
[F] +65 6873 0820
[M] +65 9873 7738
[W] www.waters.com
[E] desmond_ann@waters.com

Waters Pacific Pte Ltd
1 Science Park Road
#02-08 The Capricorn
Singapore Science Park II
Singapore 117528



From: Joel Mamalateo Deduyo <joelmamalateo.deduyo@flex.com>

Sent: Thursday, 6 August, 2020 01:46 PM

To: HuaZhen Luo <HuaZhen_Luo@waters.com>; Aldwin Pilapil <aldwin.pilapil@flex.com>; Desmond Ann <Desmond_Ann@waters.com>; Gary Lai Yam Bee <yambeegary.lai@flex.com>

Cc: Edwin Koh <Edwin_Koh@waters.com>; Nallajanula Phani Bhushan <phanibhushan.nallajanula@flex.com>

Subject: [EXT] RE: Weekly Engineering Meeting (05 Aug 2020)

ATTENTION: This email originated from outside of the organization. Please do not open any attachments or click any links unless you recognize the sender and know the content is safe.

Hi Desmond,

Niu Niu is asking if firm-up the quote for 10x 2489 Detector for tester spare usage only. Or some of this will be refurbish for shipment ?

Best Regards,



Joel Mamalateo Deduyo
Senior Test Engineer

1 Kallang Place
Singapore 339211
direct: +65 6507 5982
mobile: +65 9685 8678
email: JoelMamalateo.Deduyo@flex.com
web: flex.com

From: HuaZhen Luo <HuaZhen_Luo@waters.com>

Sent: Thursday, August 6, 2020 1:01 PM

To: Joel Mamalateo Deduyo <joelmamalateo.deduyo@flex.com>; Aldwin Pilapil <aldwin.pilapil@flex.com>; Desmond Ann <Desmond_Ann@waters.com>; Gary Lai Yam Bee <yambeegary.lai@flex.com>

Cc: Edwin Koh <Edwin_Koh@waters.com>; Nallajanula Phani Bhushan <phanibhushan.nallajanula@flex.com>

Subject: RE: Weekly Engineering Meeting (05 Aug 2020)

Hi Joel,

As per discussion, please send us quote for 4x 2489 TUV rework.

Also advise the rework time for get 4x 2489 TUV from reliability test.

Thank you

Luo HuaZhen
Senior Test Engineer



[T] +65 6593 7044
[F] +65 6873 0820
[W] www.waters.com
[E] huazhen_luo@waters.com

Waters Pacific Pte Ltd
1 Science Park Road
#02-08 The Capricorn
Singapore Science Park II
Singapore 117528



From: Joel Mamalateo Deduyo <joelmamalateo.deduyo@flex.com>

Sent: Wednesday, 5 August, 2020 19:58

To: Aldwin Pilapil <aldwin.pilapil@flex.com>; Desmond Ann <Desmond_Ann@waters.com>; HuaZhen Luo <HuaZhen_Luo@waters.com>;

Gary Lai Yam Bee <yambeegary.lai@flex.com>

Cc: Edwin Koh <Edwin_Koh@waters.com>; Nallajanula Phani Bhushan <phanibhushan.nallajanula@flex.com>

Subject: [EXT] Weekly Engineering Meeting (05 Aug 2020)

ATTENTION: This email originated from outside of the organization. Please do not open any attachments or click any links unless you recognize the sender and know the content is safe.

Hi Team,
Update for this week:

Date	RECAP:
05-Aug-20	Loss Communication : 03-Jun-2020 Shutdown TE82882-10,11 and 13 and used TE82882-8,9 and 14, data collection in progress 10-Jun-2020 TE82882-10,11 and 13 still deactivated, and checklist PM has been executed. - when to conclude? how long to run? plan end until 22 July - HZL - with TE82882-10,11 and 13 still deactivated, is the yield better? - HZL HZL/EK: suggest to continue two more week TE82882-10,11 and 13 still deactivated HZL/JMD: to confirm with production tester preference and why? NPB: production did are certain model are configured to certain Testers e.g. 2998 high runner 24-Jun-2020 TE82882- 9 and 14 configured to high runner part number (2998 family), TE82882-10 and 11 suspect to have loss comm failure Show last 2 weeks data on communication failure. WW22-WW24 start to deactivate TE82882-10,11 and 13 TE82882-9 reached 100 data points and was deactivated . Activate TE82882-13 01-Jul-2020 Refer to Manual Data Collection / SS7 server is down 08-Jul-2020 Refer to Manual Data Collection (445/600 Tested as of 07 Jul 2020 refer to Manual Collection Data for details) Based on production run rate propose to extend another until 24-Aug. 14-Jul-2020 Refer to Manual Data Collection (458/600 Tested as of 14 Jul 2020) 15-Jul-2020 To raise Evaluation Form V01 to change target date and justification due to forecast demand. 22-Jul-2020 Refer to Manual Data Collection (502/600 Tested as of 20 Jul 2020) 29-Jul-2020 Refer to Manual Data Collection (600/600 Tested as of 28 Jul 2020) 1. Check tester cables and accessories wiring and see if can find differences (Completed 09 Jul 2020 JMD) 2. Swapping CPU between high and low FPY stations to see if it's caused by CPU (Team to advise) 3. Clone high FPY station (-9) image and test it on low FPY station; (Team to advise) 05-Aug-2020 Team to discuss next action. HZL to share the 600 data to Milford (Eric Turner) and propose for the next plan. JMD to add the 600 data points summary in the CIP 2020 slide. Interface tubing Update 03-Jun-2020 To use last starting point and update the average replacement tubing. 10-Jun-2020 Data collection on-hold, received data from HZL and review / analysis for next Friday submission. - JMD: In progress reviewing 2019 SS data provided by HZL to come up with the pareto - JMD: to do the averaging of the start point 01-Jul-2020 Refer to attached pareto for 2019 using SS data. (team to review) - as per new starting point, the average replacement tubing is 22 08-Jul-2020 - No replacement perform as of to date 07 Jul 2020 14-Jul-2020 - All tubing has been replaced, will update the data collection 15-Jul-2020 - Tester #15, #16 #17 and #18 - was removed and plugged the tester filter to avoid contamination - replaced due to leak during priming #11, #12, #14 and #16. 22-Jul-2020 - Flex experienced low yield for the last 2 weeks and the troubleshooting result was retightening . We are not sure if our tech's are retightening the fittings on the UUT or the interface tubing. We interviewed them and found out that most of the time was retightening of interface tubing. 29-Jul-2020 - Plugged TE82943-11, 12,13 and 14 and unplug and installed new Interface Tubing on TE82943-14, 15, 16, 17 and 18 (27 Jul 2020) 05-Aug-2020 - TE82943-14, 15, 16, 17 and 18 and swap by 10 Aug 2020 The team concluded today to stop the evaluation of the average interface tubing replacement. Flex to continue monitor the yield. Production tester utilization, BSM QSM+ Loading as per tester. 03-Jun-2020 TUV Tester utilization added, refer to the slide. add'l May 2020 slide for 3 Family (TUV, BSM,QSM+ and PDA) 10-Jun-2020 Tracking of tester utilization in-progress for all the 3 model/family. (refer to updated slides) (need to check volume as per build plan.) - in-progress, continue monitor per build plan 24-Jun-2020 Prod'n still having low build as per build plan (KIV in Q4'2020) BSM and QSM+ Manual Priming (EVALS20019) 03-Jun-2020 Data collected as of 29 May 2020 (23/29 (79.31 FPY). UUT recovered after Retest. 10-Jun-2020 Completed Data collection for QSP as of 05 Jun 2020 26/35 (74.28%). - with Manual Priming before test. BSM to follow start from 1st WK Jul 2020 build plan, DA will check together with David today 24-Jun-2020 To be discuss as BSM start build only on 1st week Jul 2020 15-Jul-2020 - BSM Total Tested 11/35 . 10 all passed. To share before and after, pull from previous data 22-Jul-2020 11/16 PN186015001 UUT solvent line was primed prior to Final Test 3x fail due to Test Seal Wash Pump Prime/Flow 1x fail due to Test Pump A Input 2 Prime with IPA UUT able to pass after retest 29-Jul-2020 16/21 (76.19%) PN186015001 UUT solvent line was primed prior to Final Test 4x fail due to Test Seal Wash Pump Prime/Flow 1x fail due to Test Pump A Input 2 Prime with IPA UUT able to pass after retest 05-Aug-2020 18/23 (78.26%) PN186015001 UUT solvent line was primed prior to Final Test 4x fail due to Test Seal Wash Pump Prime/Flow 1x fail due to Test Pump A Input 2 Prime with IPA UUT able to pass after retest PMS SOP and Equipment List/ Asset List to send by 05 Jun 2020, purpose and usage as per current practice. 10-Jun-2020 Pls .refer to attached list and SOP - WAT-RW-SKI00709 Particle Measurement Operating Procedure to be Obsolete - get history if this procedure why not transferred to Key Point. - still need or use? - JMD (11-Jun-20) 24-Jun-2020 - To be arrange to bring back to WPPL.(HZL), JMD to initiate removal from documentations (Asset Manual, Dashboard, Calibration Master list, Consign Equipment Master List) 01-Jul-2020 - Removal from documentations (Asset Manual, Dashboard, Calibration Master list, Consign Equipment Master List) - In-progress 15-Jul-2020 - target to close 17-Jul-20 22-Jul-2020 - Removal from documentation completed 29-Jul-2020 - Team to advise for closure 05-Aug-2020 - JMD to resend the email & documentations • refer to Tooling Manual Rev B_removed the PMS

	refer to EQID 0481 Removal form from Calibration Master List JMD and HZL to work on the schedule for returning on the equipment
	2489 Lamp reliability Test Units - Scope of work 186248900 01-Jun-2020 Team to advise (KIV) 15-Jul-2020 - Quote to WPPL to Refurb to current revision. 29-Jul-2020 Reliability unit need to refurbished by : 1. Replace Ellipsoidal DT Mirror P/n: 402000170 2. Replace 402000451 Deutium Lamp 3. Reoptimize Optic Bench 4. Full Final Test 05-Aug-2020 - to get quotation from Program
	Solvent Container Cut-out window 01-Jul-2020 Gary to arrange HC to perform the agreed cut-out window 08-Jul- 2020 53 Solvent container cut-out window and plastic cover in progress 14-Jul-2020 Solvent container window has been cut-out and now placing the plastic cover (in-progress) 15-Jul-2020 placing the plastic cover (in-progress) target end of Jul '20 29-Jul2020 In-progress activity until end Sep 2020
	CCD Inquiry 05-Aug-2020 - Flex team to share information gathered 1. How many failures of CCD instance of "Carousel Malfunction" (mostly) and "Carousel Z-axis 5 malfunction in the past 6 months and percentage failed. 2. Daily verification record of carousel in Final test station. 3. Last replacement and avg frequency of replace of carousel in Final test station 4. Total number of sets of carousel in Alliance final test station. 5. PM record of both CCD alignment station.
	515 PUMP Competency Closure 05-Aug-2020 - to update by GLY after review - WPPL Eugene request for Monthly schedule for competency check. - Monthly from WPPL will be coming down for competency check. - Flex requesting WPPL to share the plan to know the date and model
	Golden Unit List 05-Aug-2020 - JDM to update the golden unit list and send to HZL - JMD to perform retest for PUMP family
	CCD Capacity Review 05-Aug-2020 - JDM & HZL to align with Program on 12 months loading number until 2021 Refer to Alliance Forecast Tab, data shows that we don't need add'l CCD station until Q4'21

Best Regards,



Joel Mamalateo Deduyo

Senior Test Engineer

1 Kallang Place

Singapore 339211

direct: +65 6507 5982

mobile: +65 9685 8678

email: JoelMamalateo.Deduyo@flex.com

web: flex.com

Legal Disclaimer :

The information contained in this message may be privileged and confidential.

It is intended to be read only by the individual or entity to whom it is addressed

or by their designee. If the reader of this message is not the intended recipient,

you are on notice that any distribution of this message, in any form,

is strictly prohibited. If you have received this message in error,

please immediately notify the sender and delete or destroy any copy of this message!

The information in this email is confidential, and is intended solely for the addressee(s). Access to this email by anyone else is unauthorized and therefore prohibited. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited and may be unlawful.



S/N	Item description	Amount in US\$	Remarks
1	Cost to rework 6units of 186248900 from reliability test to be used for Alliance final tester	2,023.67	Labor and material costs.
	Total	2,023.67	
	end of data		

Notes:
Above cost excludes 7% GST.