

DOCUMENT TITLE:	PM PROC., TE 82984 COLUMN MANAGER TESTER AND EMPOWER WORKSTATION	
DOCUMENT TYPE:	☐ Calibration	☒ Preventive Maintenance
EQUIPMENT NAME:	COLUMN MANAGER TESTER AND EMPOWER WORKSTATION	
EQUIPMENT NUMBER:	TE82984	

AUTHOR(S): **MATT BRULE**DATE: **May 19, 2016**REVISED BY: **N/A**DATE: **N/A**

EQUIPMENT REQUIRED

Quantity	Part Number	Description
None		

DISPOSABLES REQUIRED

Quantity	Part Number	Description
None		

REFERENCE DOCUMENTATION

Document Number	Description
735003678	Generic PC Maintenance Procedure
735002056	AcQuity Column Manager and Column Heater Cooler Test Procedure

1. CONECTOR INSPECTION

- 1.1. Inspect all UUT interface connectors replace any that are worn or damaged.

2. PC MAINTENANCE

- 2.1. Perform PM or TE82984 PC and the Empower Workstation per 735003678, Generic PC Maintenance Procedure.

3. MAINTENANCE COMPLETE

- 3.1. Fill out PM slip and place PM stickers on tester(s).