

Spare Parts used in Waters@Kallang Place
Jul 2019 Calibration

SUM \$ 645.11
COA \$ 64.51
Total sum \$ 709.62

S/N	Date	DESCRIPTION	Part no	BAAN No.	Quantity	Cost (US\$/EA)	Remarks
1	04-Jul-19	FAN ASSY, 4.62 IN, 85 CFM	WATH-WAT270361	WATH-WAT270361	1	\$ 14.9520	For TE82526-4 (Tester fail to home)
2	04-Jul-19	POWER SUPPLY 487 TESTED	WAT-WAT081266	WAT-WAT081266	1	\$ 56.1600	For 2487 detector golden unit
3	05-Jul-19	ASSY, PCB 2998 PDA PERSONALITY	WAT-210000404	WAT-210000404	1	\$ 265.1930	For 2998 Fine Alignment Box build (24 V fuse failed)
4	31-Jul-19	ASSY, HB DEUTERIUM LAMP	WAT-402000351	WAT-402000351	2	\$ 154.4000	For 2489 detectors s/n: B1587E610A and s/n: B1587E609A

Verified By: Ng Jie Hui 27 Aug 19