



SINGAPORE POLICE FORCE



T/20190328/2075

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

1 of 3

Report No. T/20190328/2075

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/03/2019 12:44		Vide Report No.:		Station Diary No.: 82	
Informant's Particulars					
Name of Informant: LUO HUAZHEN			Address: APT BLK 466 JURONG WEST STREET 41 #08-520 SINGAPORE 640466		
ID Type / ID No.: NRIC NO / S7760520G			Contact No.: Home/Office: Mobile: 88111989		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 41	Date of Birth: 04/04/1977	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: TEST ENGINEER			Driving Licence Information: Class: 2B,3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 27/03/2019 08:05	Type of Location: Bend
Location: Along Road 1 YUAN CHING ROAD turning into Jln Ahmad Ibrahim towards AYE				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLX5972T	Car	MITSUBISHI	ATTRAGE 1.2 CVT	Blue	Slightly Damaged	2

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLX5972T	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1800031866	02/04/2018	01/04/2020



**SINGAPORE
POLICE FORCE**



T/20190328/2075

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

2 of 3

Report No. T/20190328/2075

CONTINUATION OF REPORT

Brief Details.

On 27/03/2019 at about 0805hrs, I was driving my blue coloured car (SLX5972T) Mitsubishi Attrage along Yuan Ching Road, there are two lanes, I was on the right lane. I wish to turn to Jln Ahmad Ibrahim (Towards AYE). At that juncture, my car rear left tyre was hit by a blue coloured comfort taxi during the turning.

I saw my rear view mirror and did saw the blue coloured comfort taxi stopping at the side of the road. The traffic was very heavy at that time. As I was rushing off for a meeting, I did not stop my vehicle, I did saw the blue comfort taxi moving off as well. No one is injured from this incident. The collision causes my car rear left and rear left tyre to suffer some scratches and dent. I had lodge a report with my insurance company AIG for the claim. I do not have the plate number of the taxi and have not reported the matter to the comfort company. I have image of my damage car.



**SINGAPORE
POLICE FORCE**



T/20190328/2075

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

3 of 3

Report No. T/20190328/2075

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

D /

Sgt 2 LIH JUN JUN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / HRT /

Sr Staff Sgt ESTHER CHONG

Contact No: 65476368



SN 37

Authentication Stamp

NP168

SIGNATURE

Signature Of Informant:

Date/Time:

28/03/2019 12:44

Classification Of Case: