

Check all that apply: Add Item ☒ Remove Item ☐ Obsolete Item ☐ Adjust Interval ☐
Calibration ☒ PM ☐ Cal Not Required ☐ Other ☐

Date: 26 Mar 2021 Name: Luo Huazhen
Equipment I.D.: 10774733 Phone Number: 7044
Interval (Months): 12 Description: Digital Pressure Source
Procedure: 735004437 Location: WPPL

Part number(s) affected: TE0084040

Additional Information: _____

Note: Include justification for "Calibration Not Required"

Removing or Obsoleting Item from Calibration/PM Tracker:

Reason: N/A

Operator/ User: Luo HuaZhen Date: 26 Mar 2021

Department Manager: _____ Date: _____

Finance Manager: _____ Date: _____
(Obsolete Items Only)

Calibration Coordinator/Designee: _____ Date: _____

"N/A" if Not Applicable